

Attention Monaco, Safari, Beaver, and Holiday Rambler owners

Your Motor home was built on the Roadmaster RR4R or R4R chassis equipped with the 4 bag "Monaco gold" suspension. The control arms on the rear suspension are prone to premature failure.

Model	Production Years
Monaco Knight	2002-2004
Monaco Cayman	2002-2009
Monaco Rambler Ambassador	2002-2004
Monaco Rambler Neptune	2002-2009
Safari Cheetah	2002-2006
Safari Zanzibar / Sahara	2002-2005
Safari Simba RD	All Years
Beaver Baron	All years

Source Manufacturing LLC.

A supplier to the RV industry since 1995 has developed a solution for this problem, the TRA-1003 suspension kit (Pat.Pend.) replaces the stock control arms and includes all new and upgraded axle mounting hardware and a black powder coat finish for ultimate corrosion resistance. These kits are built to address the under sized OEM parts installed at the factory and supplied as replacement parts for field repairs. Our parts are many times stronger than the stock parts and the simple bolt in design makes installation easy for any repair facility. Even if you already had the parts replaced do to failure, the parts used are of the same design as the original. When these parts fail the damage to air springs, shocks, driveshaft etc., are common and can be very expensive. Avoid the tow bill, added cost and the weeks of delays in your travel plans and have yours replaced now.

Avoid timely and costly delays

Contact us for a dealer in your area today



Common failure pictured above

NOW AVAILABLE

RIDE ENHANCEMENT KIT – HAVE INSTALLED DURING YOUR TRAILING ARM REPLACEMENT, SAVE MONEY AND ELIMINATE YOUR ROUGH RIDE.

CALL US OR TALK TO YOUR AUTHORIZED DEALER FOR MORE INFORMATION TODAY.

Source Manufacturing LLC

Main Office: 541 935 0308

Scottz.z@source1mfg.com Cell 541-915-1149

Jim.w@source1mfg.com Cell 541-954-0046